



ATI Catalyst 4.3 Treiber verfügbar

11.03.2004 23:40

Der Grafikkartenhersteller "ATI (<http://www.ati.de>)" hat heute eine weitere Version der "ATI Catalyst" Treiber veröffentlicht. Die Treiberversion liegt nun bei "4.3". In dem Release wurden sehr viele Probleme mit Spielen behoben, sowie einiges in Sachen Leistung und Stabilität verbessert.

(Direkt zum Download, hier (<http://www.treiber-forum.de/news/id/1506/1#1>) klicken)

Changelogs: Resolved Application Issues:

This section provides information on application issues that have been resolved in the latest release of CATALYST™. These include the following: Creating a scene using 3DStudio MAX no longer results in the OpenGL window not displaying correctly when opening a context menu within the OpenGL window Dragging the Solidworks 2004 window over to the secondary display adapter no longer results in the primary display adapter displaying a highlighted image

Resolved CATALYST™ Driver Issues:

This section provides information on CATALYST™ driver issues that have been resolved in the latest release of CATALYST™. These include the following: Connecting an HDTV as the primary display with the display resolution set to 1920x1080 followed by playing a Macrovision protected DVD with the ATI DVD player no longer results in the HDTV not providing a display image when exiting the ATI DVD player A fullscreen DOS session now appears properly on the Primary display Playing an MPEG2 file with the MediaPlayer and Overlay Theater Mode enabled no longer results in the display refresh rate not being correct Enabling large desktop mode no longer results in the overlay not properly switching from one display to another

Resolved Game Issues:

This section provides information on game issues that have been resolved in the latest release of CATALYST™. These include the following: Setting the video resolution to 1280x1024 in the game Medal of Honor: Spearhead, along with Anti-Aliasing set to 2x no longer results in the main menu of the game not displaying properly Display corruption is no longer noticed when playing the game Aquanox under Windows XP with an ATI RADEON™ 9100 IGP series installed. This issue is was known to occur when specific video options have been customized Running the game Hegemonia under Windows XP with an ATI RADEON 8500 series installed no longer results in all of the main menu options and the 3D textures in the background not being available The operating system no longer fails to respond when launching the game TrackMania with a RADEON 7000 series installed Background colour corruption is no longer seen when playing the game Armed and Dangerous Poor performance is no longer noticed when playing the game Homeworld 2 with extended desktop enabled or when Anti-Aliasing is set to 4x Visual corruption is no longer seen when playing the game Spy Hunter Setting the resolution in the game Enclave to 1024x768 or higher no longer results in display corruption The Windows operating system no longer intermittently fails to respond when playing the game Jedi Knight 2 with the display set to 1024x768 32bpp and the game option set to High Quality Windows problems are no longer noticed when playing the game Homeworld 2 in single player mode Texture corruption is no longer seen when playing the game Battlefield 1942

Known Issues:

The following section provides a brief description of known issues associated with the latest version of CATALYST™. These include the following: Playing the game Nascar 2003 with the display resolution set to 1280x1024 32bpp results in display corruption being seen. This issue will be resolved in an upcoming CATALYST™ release. Further information on this issue can be found at: www.ati.com/support/infobase/4388.htmlThe demo movie Worms 3D randomly fails to properly play. Launching the movie may result in sound only being heard with no display. This issue is known to occur under Windows XP with an ATI RADEON 9800 series card installed. Further information on this issue can be found at: <http://www.ati.com/support/infobase/4405.html>Display corruption is seen when playing the demo version of the game Far Cry. Further information on this issue can be found at: www.ati.com/support/infobase/4465.htmlSetting the graphics quality to anything higher than Fastest in the game Virtual Skipper 3 results in the operating system failing to respond when the game menu loads. Further information on this issue can be found at: www.ati.com/support/infobase/4466.htmlMissing polygons on the satellite within the main menu is noticed in the game Hegemonia. Further information on this issue can be found at: www.ati.com/support/infobase/4467.htmlPlaying the game Desert Rats vs. Afirka Korps with the game resolution set to 1600x1200 and the desktop display set to 1024x768 32bpp along with Anti-Aliasing set to 4x results in flashing and or corrupt shadows. Further information on this issue can be found at: www.ati.com/support/infobase/4468.htmlEnabling multi-monitors at different display resolutions results in Direct3D or OpenGL game images appearing off center on the secondary display. Further information on this issue can be found at: www.ati.com/support/infobase/4406.html

Download:

Windows 2000/XP Treiber:

Internetverbindung	Catalyst Komponenten	Download Link	Datei Größe (MB)	Schnelle
Verbindung (DSL oder schneller)	Display Driver, Control Panel,			
WDM Capture driver		Download (http://www2.ati.com/drivers/wxp-w2k-catalyst-7-991-040224m-013831c.exe)		
1 von 1	24.3			
	Langsame Verbindung			
(Modem / ISDN)	Display Driver	Download (http://www2.ati.com/drivers/wxp-w2k-7-991-040224m-013831c.exe)		
1 von 3	8.75	Control Panel	Download	
		(http://www2.ati.com/drivers/control-panel-7-991-040224m-013831c.exe)		
2 von 3	9.98	WDM Capture driver	Download	
		(http://www2.ati.com/drivers/tv-capture-wdm-6-14-10-6227.exe)		
3 von 3	3.3			

Windows 9x/ME Treiber:

Internetverbindung	Catalyst Komponenten	Download Link	Datei Größe (MB)	Schnelle
Verbindung (DSL oder schneller)	Display Driver, Control Panel,			
WDM Capture driver		Download (http://www2.ati.com/drivers/wme-catalyst-7-991-040224m-013831c.exe)		
1 von 1	24.9			
	Langsame Verbindung			
(Modem / ISDN)	Display Driver	Download (http://www2.ati.com/drivers/wme-7-991-040224m-013831c.exe)		
1 von 3	8.75	Control Panel	Download	
		(http://www2.ati.com/drivers/control-panel-7-991-040224m-013831c.exe)		
2 von 3	9.98	WDM Capture driver	Download	
		(http://www2.ati.com/drivers/tv-capture-wdm-6-14-10-6227.exe)		
3 von 3	3.3			

Autor: [td] (thomas.deutschmann@treiber-forum.de)
 URL des Artikels: <http://www.treiber-forum.de/news/id/1506>